

Used Car appraisal form

Auto Castle Delaware 443-934-2105

Owner Details

Name: Kasey Martin
 Telephone: 609 304 5110 Fax: 302 834-8331
 Email: maxi.coates@gmail.com
 Location: 105 Ash Road Marlton NJ 08053
 Car Make & Model: 2009 Lexus LS 460
 Mileage: 246,292
 VIN #: JTHCL46R595001814

Exterior Bodywork

- Dents, scratches, rust – complete on below diagram
- Colour Blue
- Any modifications None

Interior of car

- Known Faults _____
- Fabric Condition (warn, tear, hole) Avg.
- Type of radio (cassette, cd) _____
- Any modifications _____

Mechanical

- Known Faults See Attached copy
- Any modifications _____

Documentation


- Service History Yes/No No
- Free of all liens and encumbrances Yes/No No
- Has this vehicle sustained accident/physical damage? Yes/No Amount: 2200.00
- Number of previous owners 2

Other

- Tires that need replacing now or soon: Yes/No Quantity: 4
- Alloy Wheel condition – complete on below diagram any marks
- Windscreen & other glass condition – complete on below diagram
- Number of keys 2

CODE:

X = Dent - = Scratch O = Defective Paint R = Rust C = Chips

Value
\$5200Rodney
Gron



of Wilmington

2100 Pennsylvania Avenue
Wilmington, DE 19806

Main: (302) 427-4400
(800) 456-LEXUS or (800) 456-5398

www.lexusofwilmington.com

Adv: 526 ANTHONY TRACEY		Tag 2978	License 1	JTHCL46F5 95001814	Page 1	Invoice I86681
Invoice to				Driver/Owner Information		
COATES, ROBERT 1402 WATER EDGE DR NEWARK, DE 19702 Home: (302) 476-0547				COATES, ROBERT 1402 WATER EDGE DR NEWARK, DE 19702 Home: (302) 476-0547		
For Office Use				Vehicle Information		
Odometer in: 246292 Out: 246293		INT C I Prelim		09 LEXUS LS460 4DR SDN		
				Stock#: 00123456		
Begin: 06/30/18		Done: 07/10/18		Invoiced: 07/12/18 14:35 TA		
Customer Concern						
Concern +51	CLIENT STATES THAT WHEN YOU COLD START THE ENGINE YOU HEAR A LOUD TAPPING TYPE NOISE, INSPECT AND ADVISE. NOISE FROM ENGINE BRIEFLY WHEN STARTING START VEHICLE SEVERAL TIMES, ONLY ABLE TO DUPLICATE ONCE FOR 3-5 SECONDS, NEED PROBLEM TO HAPPEN MORE CONSISTENTLY TO ACCURATELY DIAGNOSE CONCERN Tech 376 DENNEY, MICHAEL			Operation	Tech	Amount
Cause				CDC	376	0.00
Correction						
Type: I				Subtotal		
				TOTAL CHARGE FOR CONCERN 0.00		
Concern +53	CLIENT STATES THAT WHEN DRIVING YOU HEAR A THUMPING TYPE NOISE COMING FROM THE DRIVER SIDE FRONT. ROADTEST AND ADVISE. ROAD TEST VEHICLE, TIRES SEVERELY CHOPPED CAUSING NOISE, LISTEN TO WHEEL BEARING, VERY SLIGHT FROM RIGHT REAR, BAD BRAKE PULSATION NEED TO START WITH TIRE REPLACEMENT AND REPLACING FRONT PADS AND ROTORS Tech 376 DENNEY, MICHAEL			Operation	Tech	Amount
Cause				000989	376	S
Correction						
Type: I				Subtotal		
				LAB-MECHANICAL		
				TOTAL CHARGE FOR CONCERN		
Summary of Charges for Invoice I86681				Payment Distribution for Invoice I86681		
LAB-MECHANICAL				TOTAL CHARGE		
TOTAL CHARGE				INTERNAL		
X018KYWDC0:BDC						




of Wilmington

2100 Pennsylvania Avenue
Wilmington, DE 19806

Main: (302) 427-4400
(800) 456-LEXUS or (800) 456-5398

www.lexusofwilmington.com



Adv: 526 ANTHONY TRACEY	Tag 2978	License 1	JTHCL46F5 95001814	Page 2 (Last)	Invoice I86681
-------------------------	----------	-----------	--------------------	---------------	----------------

Invoice to: COATES, ROBERT	Driver/Owner: COATES, ROBERT
----------------------------	------------------------------

Invoiced: 07/12/18 14:35:06 TA	09 LEXUS LS460 4DR SDN
--------------------------------	------------------------

Attention: The following invoices also exist
CUS - CUST PAY

If you have any questions - please see ANTHONY TRACEY

SIGNATURE _____

Koons Lexus of Wilmington



Name: **COATES, ROBERT**

RO: **86681** Tag: 2978

Vehicle: 2009 LS460

Advisor: 526 - TRACEY, ANTHONY

VIN: JTHCL46F595001814 License: 1

Printed: 07/12/2018 14:35:08

Tech: 376 - DENNEY, MICHAEL

Odometer: 246,292

@F0000
31.2

CHECKED AND OK AT THIS TIME	MAY REQUIRE FUTURE ATTENTION	REQUIRES IMMEDIATE ATTENTION
------------------------------------	-------------------------------------	-------------------------------------

Green Yellow Red

	Remarks	Estimate
UNDER VEHICLE - CONTINUED		
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Visual Inspection of Rotor Condition		
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Control Arms		
UNDER HOOD		
<input type="checkbox"/> <input checked="" type="checkbox"/> Engine Quick Performance Check/Check Engine Light Illuminated	Maintenance Light On	
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Battery Terminal Condition		
<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> Battery Condition	Replace	\$208.88
<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> Engine Air Filter	Dirty	\$84.29
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Cooling System and Water Pump		
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Drive Belts (condition)		
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Induction Service		
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> FUEL INJECTION SERVICE		
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Air Conditioning Hoses and Connections/Radiator Core and Cap		
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Crankcase Ventilation System		
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Condition of Spark Plugs		
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> State Inspection/Emissions		
BG VITAL FLUID INSPECTION		
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Transmission Fluid Condition		
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Power Steering Fluid Condition		
<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> Brake Fluid Condition	Due to Mileage	\$184.90
<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> Coolant Condition	Due to Mileage	\$225.85
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Individual Tire Repair		

Comments:

Koons Lexus of Wilmington

ame: **COATES, ROBERT**

O: **86681** Tag: 2978

ehicle: 2009 LS460

Advisor: 526 - TRACEY, ANTHONY

VIN: JTHCL46F595001814 License: 1

Printed: 07/12/2018 14:35:08

Tech: 376 - DENNEY, MICHAEL

Odometer: 246,292 @F000071 31.25

CHECKED AND OK AT THIS TIME

MAY REQUIRE FUTURE ATTENTION

REQUIRES IMMEDIATE ATTENTION

Green Yellow Red

	Remarks	Estimate
INTERIOR/EXTERIOR		
<input checked="" type="checkbox"/> Interior/Exterior Bulbs	Marker Light	\$29.95
<input checked="" type="checkbox"/> Check Floor Mat Installation		
<input checked="" type="checkbox"/> Windshield Glass Inspection		
<input checked="" type="checkbox"/> Front Windshield Wiper Blade Condition		
<input checked="" type="checkbox"/> Rear Windshield Wiper Condition (if equipped)		
<input type="checkbox"/> <input checked="" type="checkbox"/> Passenger Compartment Air Filter (if equipped)	Dirty	\$91.33
BRAKE SYSTEM - Green: > 6mm/> 2mm Yellow: 4-6mm/2mm Red: < 3mm/< 2mm (Disc/Drum)		
<input type="checkbox"/> <input checked="" type="checkbox"/> Front Brake Pads	2mm	\$799.51
<input checked="" type="checkbox"/> <input type="checkbox"/> Rear Brake Pads	8mm	
<input checked="" type="checkbox"/> <input type="checkbox"/> Parking Brake System		
TIRE CONDITION - Green: > 6/32" Yellow: 4/32" - 6/32" Red: < 4/32"		
<input type="checkbox"/> <input checked="" type="checkbox"/> LF Tire Tread Depth	2/32	
<input type="checkbox"/> <input checked="" type="checkbox"/> RF Tire Tread Depth	5/32	
<input type="checkbox"/> <input checked="" type="checkbox"/> RR Tire Tread Depth	4/32	
<input type="checkbox"/> <input checked="" type="checkbox"/> LR Tire Tread Depth	4/32	
<input type="checkbox"/> <input checked="" type="checkbox"/> Tire Replacement Recommended - Green=NO Red=YES	Tread depth	\$149.80
<input checked="" type="checkbox"/> <input type="checkbox"/> Spare Tire Condition		
UNDER VEHICLE		
<input checked="" type="checkbox"/> <input type="checkbox"/> Front Suspension		
<input checked="" type="checkbox"/> <input type="checkbox"/> Rear Suspension		
<input type="checkbox"/> <input checked="" type="checkbox"/> Four Wheel Vehicle Alignment	Rec w/Replaced Tires	\$159.95
<input checked="" type="checkbox"/> <input type="checkbox"/> Engine and Transmission Mounts		
<input checked="" type="checkbox"/> <input type="checkbox"/> Check for Oil Leaks		
<input checked="" type="checkbox"/> <input type="checkbox"/> Oil Pan Gasket		
<input checked="" type="checkbox"/> <input type="checkbox"/> Transmission Pan Gasket		
<input checked="" type="checkbox"/> <input type="checkbox"/> Power Steering Rack and Pinion		
<input type="checkbox"/> <input checked="" type="checkbox"/> Front Differential (if equipped)	Due to Mileage	\$131.64
<input type="checkbox"/> <input checked="" type="checkbox"/> Rear Differential (if equipped)	Due to Mileage	\$131.64
<input type="checkbox"/> <input checked="" type="checkbox"/> Transfer Case	Due to Mileage	\$115.99
<input type="checkbox"/> <input checked="" type="checkbox"/> Constant Velocity Drive Shaft Boots	Ripped	\$1,318.79



of Wilmington

2100 Pennsylvania Avenue
Wilmington, DE 19806

Main: (302) 427-4400
(800) 456-LEXUS or (800) 456-5398

www.lexusofwilmington.com

Adv: 526 ANTHONY TRACEY		Tag 2978	License 1	JTHCL46F5 95001814	Page 1	Invoice C86681
Invoice to			Driver/Owner Information			
COATES, ROBERT 1402 WATER EDGE DR NEWARK, DE 19702 Home: (302) 476-0547			COATES, ROBERT 1402 WATER EDGE DR NEWARK, DE 19702 Home: (302) 476-0547			
For Office Use			Vehicle Information			
Odometer in: 246292 Out: 246293		CUS C I	Prelim	09 LEXUS LS460 4DR SDN		
				Stock#:	00123456	
Begin: 06/30/18	Done: 07/10/18	Invoiced: 07/12/18 14:35 TA				
Customer Concern						
Summary of charges for Invoice C86681				Payment Distribution for Invoice C86681		
TOTAL CHARGE 0.00				CASH DUE 0.00 TOTAL CHARGE 0.00		
Additional Recommendations						
DURING THE INSPECTION OF YOUR VEHICLE OUR TECHS HAVE FOUND THE FOLLOWING ITEMS ARE NEEDED:						
REPAIRS RECOMMENDED - DECLINED BY CUSTOMER:						
Item 01	Operation Concern Correction	NW Tech: 376 Follow Up: 08/01/18 RIGHT FRONT CLEARANCE LIGHT OUT REMARKS: MARKER LIGHT CUSTOMER DOES NOT WANT WORK DONE				
Item 02	Operation Concern Correction	883989 Tech: 376 Follow Up: 08/01/18 AIR CONDITIONING CABIN FILTER, FRONT, R&R (IF EQUIPPED) Remarks: Dirty AIR CONDITIONING CABIN FILTER, FRONT, R&R (IF EQUIPPED)				
Item 03	Operation Concern Correction	BR-322 Tech: 376 Follow Up: 08/01/18 (SENSOR WORN) FRONT BRAKE PADS & ROTORS, W/O HARDWARE, R&R REMARKS: 2MM FRONT BRAKE PADS & ROTORS, W/O HARDWARE, R&R				
Item 04	Operation Concern Correction	MB4 Tech: 376 Follow Up: 08/01/18 TIRES BALD ON INNER EDGE/CHOPPED/NOISY 235/50R18 Remarks: Tread depth MOUNTED & BALANCED 4 TIRES				



of Wilmington

2100 Pennsylvania Avenue
Wilmington, DE 19806

Main: (302) 427-4400
(800) 456-LEXUS or (800) 456-5398

www.lexusofwilmington.com



Adv: 526 ANTHONY TRACEY		Tag 2978	License 1	JTHCL46F5 95001814	Page 2	Invoice C86681
Invoice to: COATES, ROBERT				Driver/Owner: COATES, ROBERT		
Invoiced: 07/12/18 14:35:06 TA				09 LEXUS LS460 4DR SDN		
REPAIRS RECOMMENDED - DECLINED BY CUSTOMER:						
Item 05	Operation Concern Correction	AL4W Tech: 376 Follow Up: 08/01/18 PERFORM 4-WHEEL ALIGNMENT TO CORRECT TIRE WEAR Remarks: Rec w/Replaced Tires PERFORMED 4-WHEEL ALIGNMENT TO CORRECT TIRE WEAR				
Item 06	Operation Concern Correction	BGFDIFF Tech: 376 Follow Up: 08/01/18 PERFORM BG FRONT DIFFERENTIAL SERVICE Remarks: Due to Mileage PERFORM BG FRONT DIFFERENTIAL SERVICE				
Item 07	Operation Concern Correction	BGRDIFF Tech: 376 Follow Up: 08/01/18 PERFORM BG REAR DIFFERENTIAL SERVICE Remarks: Due to Mileage PERFORM BG REAR DIFFERENTIAL SERVICE				
Item 08	Operation Concern Correction	BGTC Tech: 376 Follow Up: 08/01/18 PERFORM BG TRANSFER CASE SERVICE ON VEHICLE Remarks: Due to Mileage PERFORM BG TRANSFER CASE SERVICE ON VEHICLE				
Item 09	Operation Concern Correction	BAT Tech: 376 Follow Up: 08/01/18 BATTERY, R&R Remarks: Replace BATTERY, R&R				
Item 10	Operation Concern Correction	AFR8A Tech: 376 Follow Up: 08/01/18 AIR FILTER, R&R Remarks: Dirty AIR FILTER, R&R				
Item 11	Operation Concern Correction	FBS Tech: 376 Follow Up: 08/01/18 VEHICLE DUE FOR BRAKE FLUID EXCHANGE SERVICE - RECOMMENDED 30,000 MILES OR 2 YEARS Remarks: Due to Mileage PERFORMED BRAKE FLUID EXCHANGE				
Item 12	Operation Concern Correction	FCS2 Tech: 376 Follow Up: 08/01/18 PERFORMED BG COOLANT SERVICE FLUSH Remarks: Due to Mileage COMPLETE COOLANT SYSTEM FLUID EXCHANGE PERFORMED.				
Item 13	Operation Concern Correction	420991 Tech: 376 Follow Up: 08/01/18 NOISE IN LR WHEEL, TIRE PRESSURE MONITOR SENSOR IF BROKEN TIRE PRESSURE MONITOR SENSOR, R&R				
Item 14	Operation Concern	BULB5 Tech: 376 Follow Up: 08/01/18 LEFT FRONT HID BULB INTERMITTENT				



of Wilmington

2100 Pennsylvania Avenue
Wilmington, DE 19806

Main: (302) 427-4400
(800) 456-LEXUS or (800) 456-5398

www.lexusofwilmington.com

Adv: 526 ANTHONY TRACEY		Tag 2978	License 1	JTHCL46F5 95001814	Page 3 (Last)	Invoice C86681
Invoice to: COATES, ROBERT				Driver/Owner: COATES, ROBERT		
Invoiced: 07/12/18 14:35:06 TA				09 LEXUS LS460 4DR SDN		
REPAIRS RECOMMENDED - DECLINED BY CUSTOMER:						
	Correction	REMOVED PANEL AND REPLACED APPROPRIATE HIGH INTENSITY XENON BULB				
Item 15	Operation Concern Correction	BULB5 Tech: 376 Follow Up: 08/01/18 RIGHT FRONT HID BULB INTERMITTENT REMOVED PANEL AND REPLACED APPROPRIATE HIGH INTENSITY XENON BULB				
Item 16	Operation Concern Correction	TPMD Tech: 376 Follow Up: 08/01/18 REPROGRAM NEW TIRE SENSOR TIRE PRESSURE MONITORING SYSTEM DIAGNOSIS				
Item 17	Operation Concern Correction	473061A Tech: 376 Follow Up: 08/01/18 REAR BRAKE ROTOR(LEFT REAR GROOVED, RIGHT REAR BELOW SPEC) REAR BRAKE ROTOR, R&R				
Item 18	Operation Concern Correction	NW Tech: 376 Follow Up: 08/01/18 BRAKE PAD WARNING LIGHT ON, RIGHT REAR SENSOR WORN CUSTOMER DOES NOT WANT WORK DONE				
Item 19	Operation Concern Correction	OFSGM Tech: 376 Follow Up: 08/01/18 OEM OIL & FILTER CHANGE OEM OIL & FILTER CHANGE				
Item 20	Operation Concern Correction	434651A Tech: 376 Follow Up: 08/01/18 BOTH FRONT DRIVE AXLE SHAFT INNER C.V. BOOTS COMPLETELY TORN, R&R Remarks: Ripped FRONT DRIVE AXLE SHAFT C.V. BOOT, R&R				
Item 21	Operation Concern Correction	SPR8I Tech: 376 Follow Up: 08/01/18 SPARK PLUGS, R&R (IRIDIUM) SPARK PLUGS, R&R (IRIDIUM)				
PLEASE GIVE US A CALL TO SET UP AN APPOINTMENT AT YOUR EARLIEST						
CONVENIENCE. THANKS.						
X018KYWDC0:BDC Attention: The following Invoices also exist INT - INTERNAL If you have any questions - please see ANTHONY TRACEY SIGNATURE _____						